

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	398562	"9" and (stress strain)	USPAT; EPO; JPO	OR	ON	2005/01/12 16:24
L2	26	((circuit near2 board) (printed near2 circuit) pc) near3 (stress strain) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5).clm.	USPAT; EPO; JPO	OR	ON	2005/01/12 16:21
L3	4	((circuit near2 board) (printed near2 circuit) pc) near3 (stress strain) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5).ti.	USPAT; EPO; JPO	OR	ON	2005/01/12 16:21
L4	1275	((circuit near2 board) (printed near2 circuit) pc) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5).ti.	USPAT; EPO; JPO	OR	ON	2005/01/12 16:23
L5	68	4 and (stress strain)	USPAT; EPO; JPO	OR	ON	2005/01/12 16:24
L6	11	5 and amplif\$6	USPAT; EPO; JPO	OR	ON	2005/01/12 16:25